

Souprava: typ DPM

Zkouška podle ČSN EN ISO 22476-2

Měřil:

Fajfr

Počet měř. úderů []: _____

Hloubka sondy [m]: 3.70

Datum zkoušky: 6.12.2017

Hlad. podz. vody [m]: neměřena

Y= 881 561.32

X= 1 059 611.35

Z= 636.54

Krok penetrování [m]: 0.10

Souř. systémy: JTSK / Balt

Hloubka [m]	Počet úderů		Qd [MPa]	Hl. [m]	Graf penetrace											Geologická charakteristika
	měř.	red.			10	20	30	40	50	60	70	80				
0.1	1															
0.2	1															
0.3	3															
0.4	6															
0.5	6															
0.6	5															
0.7	4															
0.8	5															
0.9	4															
1.0	5															
1.1	4															
1.2	5															
1.3	6															
1.4	6															
1.5	6															
1.6	5															
1.7	6															
1.8	6															
1.9	6															
2.0	12															
2.1	12															
2.2	11															
2.3	11															
2.4	12															
2.5	12															
2.6	15															
2.7	15															
2.8	17															
2.9	20															
3.0	22															
3.1	33															
3.2	40															
3.3	55															
3.4	53															
3.5	37															
3.6	59															
3.7	70															

Název akce: **Lesná - mosty**

Měřítko: 1:50

Zak. číslo: 17/563

Dokumentoval: RNDr. M. Fajfr

Vyhodnotil: RNDr. M. Fajfr

Zpracoval: RNDr. M. Fajfr

Příloha č.: **5.1**